



# Chalmette Slip

## 06-08-2023

### Elevations Tide 5.0

Survey Depth Values Are Corrected  
To NGVD Zero Gauge At  
New Orleans - Carrollton Gauge  
All Drawings Are For Dredging Purposes Only





RIVER FLOW ->




**MAINTENANCE  
Dredging I, LLC**

*A Professional Dredging Company*

# Chalmette Slip 06-08-2023 Elevations Tide 5.0

Survey Depth Values Are Corrected  
To NGVD Zero Gauge At  
New Orleans - Carrollton Gauge  
All Drawings Are For Dredging Purposes Only





# Chalmette Slip

## 06-08-2023

### Elevations Tide 5.0

Survey Depth Values Are Corrected  
To NGVD Zero Gauge At  
New Orleans - Carrollton Gauge  
All Drawings Are For Dredging Purposes Only

